

INSPECTION REPORT MOVE-OUT

Name: Brenda Bennet

Email: BrendaJBennett@teleworm.us

4556 Black Oak Hollow Road Sunnyvale CA CA 94086

Contract from 6/17/2017 to 9/22/2017

Unit

Building: Old Graduate College

Floor: Floor 1 Unit: Suite 101 Room: Bedroom 1

Inspected By: William Johnson On: Thursday, September 28, 2017

Building: Old Graduate College Floor: Floor 1 · Unit: Suite 101

Room Nr.: Bedroom 1

ISSUES

OLD GRADUATE COLLEGE · FLOOR 1 SUITE 101 / BEDROOM 1 / BASICS / DOOR HANDLE

Type Damage Action To Repair

ObservationDate 4/4/2017 58291




OLD GRADUATE COLLEGE · FLOOR 1 SUITE 101 / BEDROOM 1 / FURNITURE & DECORATION / MATTRESS 2

Type Dirty

Action To Replace

ObservationDate 4/4/2017 58292



CHECKLIST

Remove personal items	
Clean room	
Return key & badges	
Confirm leaving	
Address Forwarding	

Building: Old Graduate College Floor: Floor 1 · Unit: Suite 101

Room Nr.: Bedroom 1

CLAUSES

- 1. The purpose of this inspection is to perform limited, visual and auditory on site observations of the readily accessible areas of the primary structure, mechanical, and electrical systems of the building and to give a personal opinion as to whether or not the components of the room are performing the function they were intended or are in need of immediate repair. This report is not all encompassing nor is it meant to be. It is very specific in the areas which are reported by the home inspector.
- 2. This inspection is made and managed digitally. All pictures are digital, are part of it and can be used as evidence.

SIGNATURES

Unit

Building: Old Graduate College

Floor: Floor 1 Room: Bedroom 1

Unit: Old Graduate College

Tenant

Brenda Bennet

4556 Black Oak Hollow Road Sunnyvale CA CA 94086

Inspector

William Johnson

Tenant Signature

Inspector Signature

