



INSPECTION REPORT MOVE-OUT

Name : Michael Billman
Email : m.billman@jourrapide.com
156 South Street
Houston TX TX 77026
Contract from 6/18/2018 to 10/26/2018

Building : Bleinheim
Floor : Floor 1
Unit : Room 1
Room : Bedroom

Inspected By : William Johnson
On : Tuesday, October 30, 2018

ISSUES

BLEINHEIM · FLOOR 1 ROOM 1 / BEDROOM

Action To Repair
ObservationDate 6/18/2018 171169


BLEINHEIM · FLOOR 1 ROOM 1 / BEDROOM / BASICS / CEILING

Type Damage
Action To Replace
ObservationDate 10/30/2018 210475



BLEINHEIM · FLOOR 1 ROOM 1 / BEDROOM / BASICS / DOOR HANDLE

Type Damage
Action To Replace
ObservationDate 6/18/2018 171170



BLEINHEIM · FLOOR 1 ROOM 1 / BEDROOM / FURNITURE & DECORATION / BIN

Type Damage
Action To Replace
ObservationDate 10/30/2018 210476

BLEINHEIM · FLOOR 1 COMMON ROOMS / KITCHEN / FURNITURE & DECORATION / SINK

Type Damage
Action To Repair
ObservationDate 6/18/2018 171171

CHECKLIST

Remove personal items



- Clean room
- Return key & badges
- Confirm leaving
- Address Forwarding

CLAUSES

1. The purpose of this inspection is to perform limited, visual and auditory on site observations of the readily accessible areas of the primary structure, mechanical, and electrical systems of the building and to give a personal opinion as to whether or not the components of the room are performing the function they were intended or are in need of immediate repair. This report is not all encompassing nor is it meant to be. It is very specific in the areas which are reported by the home inspector.
2. This inspection is made and managed digitally. All pictures are digital, are part of it and can be used as evidence.

SIGNATURES

Unit

Building: Bleinheim
Floor: Floor 1
Room: Bedroom
Unit: Bleinheim

Tenant

Michael Billman
156 South Street
Houston TX TX 77026

Inspector

William Johnson

Tenant Signature

Inspector Signature